

## Remanufactured Unit Charge Back Guide\*

Hole in case or housing:

- Transfer case 25% (exploded 50%)
- Transmission 25% (exploded 50%)
- Differential (Bad Spindle, Crack/Hole in Housing) 50%

Disassembled units	\$150.00
Oil not drained completely	\$100.00
Core returned without shipping tote	\$150.00
Shipping tote returned without core	No Credit
Tote hardware not returned (Straps)	\$25.00
Remanufactured unit not like for like	No Credit

\*All charge backs will be deducted from Core Return Value

## Remanufactured Unit Charge Back Guide\*

Hole in case or housing:

- Transfer case 25% (exploded 50%)
- Transmission 25% (exploded 50%)
- Differential (Bad Spindle, Crack/Hole in Housing) 50%

Disassembled units	\$150.00
Oil not drained completely	\$100.00
Core returned without shipping tote	\$150.00
Shipping tote returned without core	No Credit
Tote hardware not returned (Straps)	\$25.00
Remanufactured unit not like for like	No Credit

\*All charge backs will be deducted from Core Return Value